TO BE FILLED BY THE INSPECTING OFFICER

: SIRAJULHUDH ENCILISH MEDILING SCHOOL 1. Name of School : RAJAN-KIK-(ASSISTANT ENGINEER) 2. Name of Officer · PERINGATAUR 3. Location : 2022 Period for which the certificate is issued : Rec BUILDING. Types of building Gif - 8.60x 19 10x3.75m). 8.60 x 19.10x 3.75 m Nature of defect if any 39-90x 8-60x3.75ma) Foundation and basement FF - 8-60 x 19.10 x 3-75 m. b) Super structure 8-to x19-10 x3-75m c) Doors and windows d) Wood work wrought and put up 39.90 x 8.60 x 3.75 m. e) Roof SF - 8-60×19-10×3-75m n Flooring g) Miscellaneous 8- hox 19.10 x 2.75m. 39.96 X 8-60 X3-75 m. 7. Any major defects notice which will render : WIL the building unsafe in any manner

9. Whether the structure is sound for conducting: Structure is Sound for conducting

Classes at normal wrong and weather

: YES.

Note: 1. The stability of the structure should be examined also with reference to the altitude, intensity of wind exposure to flood etc.

 Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate

Certified that the School was inspected by on 21/03/2022 and found to be fit to conduct classes for the period for the reasons stated above from 21/03/2022 to 31/12/2022

Place: Danbor

8. Whether maintenance works have been

Assistant Engineer
Assistant Engineer

Assistant Engineer

Municipality

Papoor P. O. Kassur Dist. of 692

Signatu

PRINCIPAL Sirajul Huda English Medium School Peringathur MANAGER
SIAAJUL HUDA ENGLISH MEDIUM SCHOOL
PERINGATHUR